

GX120/140/160/200/240/270/340/390 **Carburetor Check Sheet**





Valve seat worn or coated with foreign materials/





Remove foreign materials/dirt.

Check of float chamber (12)Water inside Float chamber cause engine failure. Take off Float chamber and clean or replace.

10

© Honda Motor Co., Ltd. Power Product Service Division 2004.12